

**HUD
Engineering Certification
Report**

[Redacted]

[Redacted]

Prepared for: [Redacted]



Registered Field Technician

POMI Services

850-586-1934

operations@pomiservices.com

Engineer

[Redacted]

[Redacted]

[Redacted]

Table of Contents

Table of Contents	2
General	3
Client & Site Information	3
Climatic Conditions	3
Building Characteristics	4
Structural	6
Structure - Foundation	6
Additions	8
Exterior Steps/Stoops Addition	8
Exterior Steps/Stoops Addition	9
Covered Porch Addition	10
Terms and Conditions	12

General

Client & Site Information

1.1 Inspection Date

January 14, 2025 01:04 PM

1.2 Client



1.3 Inspection Site



1.4 Address Image



1.5 Vacancy

Vacant

Climatic Conditions

1.6 Weather

Clear and None

1.7 Soil Conditions

N/A

1.8 Outside Temperature

56°



Building Characteristics

1.9 Elevation Pictures



1.10 Date of Manufacture

2007

1.11 Building Type

Single-wide


1.12 Rough Exterior Dimensions

16' x 68'

1.13 HUD Label 1



1.14 Data Sheet



1.15 Foundation Type

Isn

1.16 Foundation Type Images



1.17 Interior Support Structure

Concrete Masonry Units

1.18 Piers Rest On

Plastic Pad

1.19 Wheels

Wheels and axles are Removed

1.20 Tongues

Removed from Frame



Structural

Structure - Foundation

2.1 Exterior Grading

Grading is flat but no adverse conditions were noted.

2.2 Exterior Grading Images



2.3 Skirting

Vinyl

2.4 Anchor Method

Metal Straps anchored into a concrete slab and/or footings (spacing every 5 feet)

2.5 Anchor Method Images



Additions

Exterior Steps/Stoops Addition

3.1 Location

Front


3.2 Images



3.3 Floor Structure Assessment

No loads are being transferred from the floor structure onto the structure of the manufactured home.

3.4 Floor Structure Images



3.5 Roof Structure Assessment

No loads are being transferred from the roof structure onto the structure of the manufactured home.

3.6 Roof Structure Images



3.7 Modification Statement

The Mfd. home **does not appear to have been** modified or altered with respect to this addition.

Exterior Steps/Stoops Addition

3.8 Location

Right Side

3.9 Images



3.10 Floor Structure Assessment

No loads are being transferred from the floor structure onto the structure of the manufactured home.

3.11 Floor Structure Images



3.12 Roof Structure Assessment

No roof structure present.

3.13 Modification Statement

The Mfd. home **does not appear to have been** modified or altered with respect to this addition.

Covered Porch Addition

3.14 Location

Back/Rear

3.15 Images



3.16 Floor Structure Assessment

No loads are being transferred from the floor structure onto the structure of the manufactured home.

3.17 Floor Structure Images



3.18 Roof Structure Assessment

No loads are being transferred from the roof structure onto the structure of the manufactured home.

3.19 Roof Structure Images



3.20 Modification Statement

The Mfd. home **does not appear to have been** modified or altered with respect to this addition.

HUD Engineering Certification Report Summary

Date: January 15, 2025

Client: [REDACTED]

Permanent Foundation

As requested, we have evaluated the site conditions and foundation of the existing manufactured home for conformance with the Permanent Foundation Guide for Manufactured Housing; September, 1996. The purpose of this evaluation is for the resale, purchase, financing, or refinancing of the home. Our investigation and evaluation has been based on a visual review of the readily accessible areas of the foundation and overall surrounding site. The scope of the inspection included the foundation of the house.

On January 14, 2025 01:04 PM, we made a site visit to evaluate the site drainage conditions and house foundation.

We observed that the manufactured structural frame of this Single-wide house is supported permanently to a foundation in the crawlspace. We observed that horizontal and vertical uplift restraint had been provided at various locations. The manufactured frame had been fastened to the foundation adequately. The overall integrity of the foundation was in good condition. Based on the information observed, we are of the opinion that the house foundation has been constructed in accordance with HUD/FHA Guidelines - Permanent Foundation Guide for Manufactured Housing HUD-4930.3G; September, 1996. The foundation meets HUD guidelines for manufactured housing dated Sept 1996.

The HUD PFGMH is a minimum standard for tie-down systems required to meet federally-backed loan requirements. Even with tiedown systems that meet the most stringent standards, mobile and manufactured homes are considered unsafe structures in violent or extreme weather such as, but not limited to, severe thunderstorms, floods, derechos, tornados and hurricanes.

Additions

As requested, we have inspected the requested addition(s) (Exterior Steps/Stoops addition, Exterior Steps/Stoops addition, and Covered Porch addition) of the existing manufactured home for conformance with HUD Guidelines for Manufactured Housing 1996. The purpose of this evaluation is for the resale, purchase, financing, or refinancing of the home. Our investigation and evaluation has been based on a visual review of the readily accessible areas of the Exterior Steps/Stoops addition, Exterior Steps/Stoops addition, and Covered Porch addition.

On January 14, 2025 01:04 PM, we made a site visit. Based on the information observed, we are of the opinion that:

No loads of potential significance are being transferred from any existing addition onto the manufactured home. The manufactured home is in compliance with HUD Guidelines.

1st Permanent Location

No visible on-site evidence was noted or observed which would indicate that the Manufactured home was moved from another "permanent" location.

If you have any questions or need clarification regarding this report, please contact Richard Hood of POMI Services at 850-586-1934 or email operations@pomiservices.com. Thank you.

Sincerely,

[REDACTED]

[REDACTED]



POMI Services

850-586-1934

operations@pomiservices.com

Terms and Conditions

This Report is expressly made subject to the following terms and conditions to which all persons that receive and rely thereon agree:

1. Said Report is given with the skill and care ordinarily used by members of the engineering profession practicing under similar conditions at the same time and in the same locality and applies only to facts that are within Engineer's knowledge or could reasonably have been ascertained by ENGINEER.
2. Said Report reflects and is an expression of the professional judgment of ENGINEER.
3. Said Report is given as to the best of Engineer's knowledge, information, and belief as of the date hereof.
4. Said Report is based entirely on and expressly limited by the scope of services ENGINEER has been employed by Client to perform.
5. To the fullest extent permitted by law, Client and Engineer (1) waive against each other, and the other's employees, officers, directors, agents, insurers, partners, and consultants, any and all claims for or entitlement to special, incidental, indirect, or consequential damages arising out of, resulting from, or in any way related to this report, and (2) agree that Engineer's total liability to Client shall be limited to the total amount of compensation received by Engineer.
6. This Report was produced and provided for the Client by the ENGINEER or his assistant trained in these inspections working directly under the supervision of the ENGINEER.
7. The parties acknowledge that Engineer's scope of services does not include any services related to a Hazardous Environmental Condition (the presence of asbestos, PCBs, petroleum, hazardous substances or waste, and radioactive materials).
8. This inspection is only for compliance with HUD Guidelines and does not include or address local or state guidelines, other building codes or jurisdiction requirements.

