4 i onit mapeotion i orm					
Insured/Applicant Name:		Application / Policy #:			
Address Inspected:					
Actual Year Built: 1979		Date Inspected: 11	/25/2024		
Minimum Photo Requirements  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ ☑ Main electrical service panel with interior doo ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this re A Florida-	or label				
			s obtained from the Florida licensed professional of ce of the suitability, fitness or longevity of any of the		
Electrical System Separate documentation of any aluminum wiring r	remediation must be provid	ded and certified by a lic	ensed electrician.		
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 100  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)			
Indicate presence of any of the following:					
□ Cloth wiring □ Active knob and tube □ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. □ Connections repair via COPALUM crimp □ Connections repair via AlumiConn					
Hazards Present  ☐ Blowing fuses ☐ Empty sockets ☑ Loose Wiring ☐ Tripping breakers ☐ Improper grounding ☐ Corrosion ☐ Double taps		□ Exposed wiring □ Over fusing □ Unsafe wiring □ Improper breaker size □ Scorching □ Other (explain)			
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: Original	Panel age: Original		<b>☑</b> Copper		
Year last updated: Unknown	Year last updated: <u>Unknown</u>		□ NM, BX or Conduit		

Brand/Model: Square D

Brand/Model: Milbank

Central AC:				
If not central heat, indicate primary heat source and fuel type:				
Are the heating, ventilation and air conditioning systems in good working order?				
Hazards Present  Wood burning stove or central gas fireplace not professionally installed?				
Hazards Present  Wood burning stove or central gas fireplace not professionally installed?   Yes  No    Space heater used as primary heat source?   Yes  No    Is the source portable?   Yes  No    Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?				
Wood burning stove or central gas fireplace not professionally installed?   Yes				
Space heater used as primary heat source?   Yes				
Is the source portable?				
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?    Yes				
Supplemental Information  Age of system: 2021 Year last updated: 2021 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)  Plumbing System  Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Laundry/Age 2024  General condition of the following plumbing fixtures and connections to applicances:  Satisfactory Unsatisfactory N/A Dishwasher Satisfactory Unsatisfactory N/A Dishwasher Sinks				
Age of system: 2021  Year last updated: 2021  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)  Plumbing System  Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Laundry/Age 2024  General condition of the following plumbing fixtures and connections to applicances:  Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A Dishwasher Yes Sinks Yes Company Co				
Year last updated: 2021(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)  Plumbing System  Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location:				
Plumbing System  Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Laundry/Age 2024  General condition of the following plumbing fixtures and connections to applicances:  Satisfactory Unsatisfactory N/A Dishwasher Yes N/A Dishwasher N/A				
Plumbing System  Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No  Is there any indication of an active leak? ☐ Yes ☑ No  Is there any indication of a prior leak? ☐ Yes ☑ No  Water heater location:				
Is there a temperature pressure relief valve on the water heater? Yes No  Is there any indication of an active leak? Yes No  Is there any indication of a prior leak? Yes No  Water heater location:  Laundry/Age 2024  General condition of the following plumbing fixtures and connections to applicances:  Satisfactory Unsatisfactory N/A  Dishwasher Meater Meater Meater Meater Main shut off valve Meater				
Is there any indication of an active leak?				
Is there any indication of a prior leak?				
Water heater location:    Laundry/Age 2024				
General condition of the following plumbing fixtures and connections to applicances:  Satisfactory Unsatisfactory N/A  Dishwasher				
Satisfactory Unsatisfactory N/A  Dishwasher  Refrigerator  Washing Machine  Water Heater  Satisfactory  N/A  Toilets  Sinks  Sinks  Main shut off valve  Main shut off valve  N/A  Toilets  Satisfactory  Unsatisfactory  N/A  Dishwasher  N/A  Satisfactory  N/A  Satisfactory  N/A  Dishwasher  N/A  Dishwasher  N/A  Main shut off valve  N/A  Main shut off valve  N/A  Dishwasher  N/A  Main shut off valve  N/A  Dishwasher  Dishw				
Dishwasher				
Refrigerator         ✓         ✓         ✓         ✓         ✓         ✓         ✓           Washing Machine         ✓         ✓         ✓         Sump pump         ✓         ✓         ✓           Water Heater         ✓         ✓         ✓         ✓         ✓         ✓         ✓				
Washing Machine   ☐ ☐ ☐ Sump pump ☐ ☐ ☐  Water Heater ☐ ☐ Main shut off valve ☐ ☐ ☐				
Snowers/Tubs   All other visible   L				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
And of Dining Contamy				
X Original to home				
- I <del>v</del> i Coppei				
Completely re-piped ☑ PVC/CPVC				
Partially re-piped Galvanized  (Provide year and extent of renovation in the comments below)				
TO TOWN YOU AND CALOU OF TO TO TOWN THE TO CONTINUE SOLOWY TO THE TEXT				
□ Polybutylene				

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i> )						
Predominant Roof		Secondary Roof				
Covering material: Architectural Shingles		Covering material:				
Roof age (years): 3		Roof age (years):				
Remaining useful life (years): 15+ Date of last roofing permit: 07/21/202	1	Remaining useful life (years):				
Date of last update: 07/21/2021	<u> </u>	Date of last roofing permit:  Date of last update:				
If updated (check one):		If updated (check one):				
☑ Full Replacement		☐ Full Replacement				
☐ Partial Replacement		☐ Partial Replacement				
% of replacement		% of replacement				
Overall condition:		Overall condition:				
☑ Satisfactory		☐ Satisfactory	☐ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterior	oration?	Any visible signs of damage / deteri	oration?			
(check all that apply and explain below	)	(check all that apply and explain below	))			
☐ Cracking		☐ Cracking				
☐ Cupping/Curling		☐ Cupping/Curling	☐ Cupping/Curling			
☐ Excessive granule loss		☐ Excessive granule loss	☐ Excessive granule loss			
☐ Exposed asphalt		☐ Exposed asphalt	$\square$ Exposed asphalt			
☐ Missing/loose/cracked tabs or tile	es	☐ Exposed felt				
☐ Exposed felt		☐ Missing/loose/cracked tabs or tile	es			
☐ Soft spots in decking		☐ Soft spots in decking				
☐ Visible hail damage		☐ Visible hail damage				
☐ Missing shingle		Any visible signs of leaks ☐ Yes ☐	_			
Any visible signs of leaks ☐ Yes ☑ No		Attic/underside of decking ☐ Yes ☐ N	No			
Attic/underside of decking ☐ Yes ☑ No		Interior ceilings ☐ Yes ☐ No	Interior ceilings ☐ Yes ☐ No			
Interior ceilings ☐ Yes ☑ No						
Additional Comments/Observations(use additional pages if needed):						
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.						
I certify that the above statements are true and correct.						
× 68	Home Inspector	HI13314	11/25/2024			
Inspector Signature	Home Inspector Title	License Number	Date			
POMI Services	Home Inspector	850-586-1934				
Company Name	License Type	Work Phone	<del>-</del>			

**Special Instructions:** This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# **Photos, Additional Comments or Observations**

### **Exterior Photos**



## **Electrical System**

Panel Photos





Hazards




## **HVAC System**

**HVAC** Equipment








## Plumbing System

Water Heater



Kitchen



Bathroom #1



Laundry Room



**Roof**Photos of Each Slope



